DMV Technician: 62 and 170 Best Position 1 or 2			
Station: W//W Date: /-/8 Time:		12:4	3
Vehicle Make: Merc Model MLN	Year	200	
GVWR: Fuel Type: Registration N			765 4/
Auditor: Covered Covert Overt	(circle	one)	
1 201 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	-		
2. Was Emissions testing required?	1		
a) Was Emissions testing performed using OBD?			
b) Was Emissions testing performed using Analyzer Probe?			
c) Was Emissions testing performed using Paddle(s)?			
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?		- 2	_
a) Was Catalytic Converter inspection performed?			-
4. Was Fuel Tank pressure testing required?			(
a) Was Fuel Tank pressure testing performed?			
5. Was Fuel Cap pressure testing required?			4
a) Was Fuel Cap pressure testing performed?			
6. Is this test a Re-check from a prior failure?			-
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only		X	X
7. Was Two-Speed Idle testing required?			
a) Was Two-Speed Idle testing performed?			
	74		
Sussex County Only	1		
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?	4		
Comment:			

DMV Technician: Benni frest No Bert Position: 1 or 2			
Station: wi/m Date: /- 18-20/Time:		300	0
Vehicle Make: Tagosa Model —	Year /		
GVWR: Fuel Type: 645 Registration N	umber:		
Auditor: Covert/Overt	(circle	one)	
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	1		
2. Was Emissions testing required?	-		
a) Was Emissions testing performed using OBD?			
b) Was Emissions testing performed using Analyzer Probe?	-		
c) Was Emissions testing performed using Paddle(s)?			
d) Was Emissions testing performed using Clip?	-		
3. Was Catalytic Converter inspection required?	1		
a) Was Catalytic Converter inspection performed?	-		
4. Was Fuel Tank pressure testing required?			4
a) Was Fuel Tank pressure testing performed?		-	
5. Was Fuel Cap pressure testing required?	-		
a) Was Fuel Cap pressure testing performed?	~		
6. Is this test a Re-check from a prior failure?			
a) Which re-check test is being performed? 1 2 3 (circle one)		1	
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only			
7. Was Two-Speed Idle testing required?	4		
a) Was Two-Speed Idle testing performed?			
Sussex County Only			
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment:			
54 THW 1747 PC 683874			
as TOOK ADAPTER HAID HIME TO OH	n -		

DMV Technician: Ro deriquez Stave Position: 1 or 2 Station: W/M Date: 18-13 Time: 160 Vehicle Make: Vissan Model Scarin Year 2003			
Station: W/M Date: 18-13 Time	Time: 1. 60		
Vehicle Make: VISSAN Model Serin	Year	200	3
GVWR: Fuel Type: Registration N	lumber:	54	503
Auditor: Covert Over	t (circle	one)	
		1	
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	4		
2. Was Emissions testing required?	-		
a) Was Emissions testing performed using OBD?	1		
b) Was Emissions testing performed using Analyzer Probe?			
c) Was Emissions testing performed using Paddle(s)?	7		
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?		1	
a) Was Catalytic Converter inspection performed?			
4. Was Fuel Tank pressure testing required?		-	
a) Was Fuel Tank pressure testing performed?			
5. Was Fuel Cap pressure testing required?		-	
a) Was Fuel Cap pressure testing performed?			
6. Is this test a Re-check from a prior failure?		1	
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only			
7. Was Two-Speed Idle testing required?		-	
a) Was Two-Speed Idle testing performed?			
Sussex County Only			
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment:			

	on:1 or 2		
Station: 1/8+3 Time		06	
Vehicle Make: V 155 PM Model MAX	Year	19	93
GVWR: Fuel Type: 6 A 5 Registration N			Be/o
Auditor: Coverdale Covert / Over	t (circle	one)	
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	~		
2. Was Emissions testing required?	L		
a) Was Emissions testing performed using OBD?	1		1.
b) Was Emissions testing performed using Analyzer Probe?	-		
c) Was Emissions testing performed using Paddle(s)?	-		
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?	6		
a) Was Catalytic Converter inspection performed?	~		
4. Was Fuel Tank pressure testing required?		-	
a) Was Fuel Tank pressure testing performed?			-
5. Was Fuel Cap pressure testing required?	1		
a) Was Fuel Cap pressure testing performed?	-		
6. Is this test a Re-check from a prior failure?		-	
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only			
7. Was Two-Speed Idle testing required?	6		la e e
a) Was Two-Speed Idle testing performed?	~		
Sussex County Only			
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment: JN 14JO1 FO PTO 9 9378			
CAN I/A HAID LINE			